

## **ASBESTOS CLEARANCE CERTIFICATE INSPECTION PASS**

**Project/Location:** 115 Gladstone Street, Fyshwick, ACT 2609

**Job Number:** H2466

**Client:** Empire Contracting

**Client Contact:** Steven Simpson – 0413 396 785

**Time and Date of Inspection:** 12:50 on Friday, 18 January 2019

**Date(s) and Description of Work:** Removal/remediation of non-friable asbestos cement sheet from the ceiling in the kitchenette, ceiling in the hallway to the ablutions and the ceiling in the ablutions and shower. Removal of debris and packers under the site office subfloor and painting/sealing of packers that was not able to be removed.

**Date of Report:** 18/01/2019

**Asbestos Removelist:** Empire Contracting

### **Certification:**

A visual inspection was carried out on Friday, 18 January 2019, by Marcus Brooks following the completion of the asbestos works listed above in accordance with Robson Environmental's NATA, ISO9001, ISO14001 and AS4801 accreditations. It should be noted that this clearance certificate relates only to the exact area(s) specified above.

The inspection found no visible asbestos residue from the asbestos work in the area or in the vicinity of the area where the work was carried out.

Refer to Appendix A for Photograph(s).

The work area has been given the "all clear" and restrictions associated with the asbestos works can now be lifted and the area safely reoccupied.

Authorised by:



Marcus Brooks – Licensed Asbestos Assessor - #2318451

Occupational Hygienist

Mobile: 0411 826 933

**Appendix A – Photo(s)**



PHOTO NO	LOCATION DESCRIPTION	PHOTOGRAPH
1	After removal of non-friable asbestos cement sheet from the ceiling in kitchenette	
2	After removal of non-friable asbestos cement sheet from the ceiling in hallway joining the kitchenette and the ablutions	<p data-bbox="715 1323 810 1384">Bolts not nails</p> 



PHOTO NO	LOCATION DESCRIPTION	PHOTOGRAPH
3	After removal of non-friable asbestos cement sheet from the ceiling in the ablutions	
4	After removal of non-friable asbestos cement sheet from the ceiling in shower	



PHOTO NO	LOCATION DESCRIPTION	PHOTOGRAPH
5	After removal of non-friable asbestos cement sheet packers under the office subfloor	
6	After removal of non-friable asbestos cement debris under the office subfloor	



PHOTO NO	LOCATION DESCRIPTION	PHOTOGRAPH
7	Painting of in-situ presumed asbestos packers	